Approved For Release 2001/07/28 : CIA-RDP75B00446R000100200042-4

FORM 9-72 2820 USE PREVIOUS EDITIONS

(44)

CLASSIFIED MESSAGE

IMMEDIATE

FILE INFO

REPRODUCTION PROHIBITED

28 APR 74 14 55Z

ACTION							
	1	6	11	16			
	2	7	12	17			
	3	8	13	18			
	4	9	14	19			
	5	10	15	20			

CHIEF

ENG SUP

TEL CPS

ADMIN

FILE

29 APR 1974

S E C R E T 281400Z APR 74 CITE [redacted]

25X1A

25X1A IMMEDIATE [redacted]

25X1A [redacted]

25X1A

REF [redacted]

1. FAILURES CAN NOT BE CONTRIBUTED CONTINUOUS OPERATION. PROBLEMS THUS FAR IDENTIFIED AS FOLLOWS:

A. 546T-1 LINEAR POWER AMPLIFIER: C-54 DISINTEGRATED, L-28 BURNED BUT CONDITION UNKNOWN. OTHER LPA NOW OKAY.

B. 656X-2 POWER SUPPLY: DIODE FOR 400 HERTZ FOR 115VAC SUPPLY SHORTED.

NO PHYSICAL SIGNS DAMAGE OTHER PWR SUPPLY BUT STILL FAULTY. LACK OF TEST JIG OR ADEQUATE TEST EQUIPMENT MAKES CHECKS DIFFICULT.

25X1A

2. IN ADDITION SLICES IDENTIFIED REF A PARA 1, RECOMMEND [redacted] BRING FAULTY COMPONENTS NOTED PARA 1 ABOVE.

3. HAVE CONSIDERED HFL-1000 BUT LOCATION PRECLUDES ERECTION

25X1A

HFAS-9 OR SIMILAR ANTENNA. WE LIMITED TO WHIPS; HOWEVER, WILL CHECK [redacted] AND ADVISE. PREFER SPARE SLICES FOR A/C PACKAGES RATHER THAN USE KILOWATT RIG DUE SPACE LIMITATION. HAVE ON HAND ONE ~~COMPLETE SPARE "B" PAC~~

Approved For Release 2001/07/28 : CIA-RDP75B00446R000100200042-4

Approved For Release 2001/07/28 : CIA-RDP75B00446R000100200042-4

CLASSIFIED MESSAGE

FILE INFO

REPRODUCTION PROHIBITED

ACTION	1		6		11		16	
	2		7		12		17	
	3		8		13		18	
	4		9		14		19	
	5		10		15		20	

COMPLETE SPARE "B" PACKAGE. PROBLEM ALL RELATED A AND C PACKAGES. THE SPEEDY RESPONSE AND ACTION ON PART [redacted] IN RESPONSE OUR CRY FOR HELP GREATLY APPRECIATED. E-2 IMPDET 25X1A

S E C R E T

BT

Sen 11 215 Encl
28 APR 74
[redacted]

Approved For Release 2001/07/28 : CIA-RDP75B00446R000100200042-4